



Notes:

1. This wiring diagram may also be used with 0-100% oxygen transmitter 65-2322RK-100.

DO NOT SCALE DRAWING

Deburr Break Edges .010 R

All Dimensions In Inches Unless Otherwise Noted.

MATERIAL: N/A

FINISH: N/A

SCALE: None



RKI Instruments, Inc.

www.rkiinstruments.com

TITLE: Wiring Diagram, 65-2322RK to Pioneer

A

DRAWN
BY: DJPART NUMBER:
65-2322RK-R08REVISION:
P1

APPROVED BY:

DATE: 11/13/07

PAGE 1 OF 1

Tolerances & Finishes Unless Otherwise Noted:

.XX ± .010 Angles ± 0° 30'

.XXX ± .005 Conc. .010 TIR

Fractions ± .015 Finish 125/32

Finish for O-ring Grooves, 3 Sides