RIKEN HC 0-100%LEL to 0-100 vol% auto ranging and O<sub>2</sub> 0-25 vol% or CH<sub>4</sub> 0-100%LEL to 0-100 vol% auto ranging and O<sub>2</sub> 0-25 vol%

## PORTABLE COMBINATION HC/O2 GAS DETECTOR









### Highly accurate & reliable

# RX-415

#### OUTLINE

This model has two versions and is a combination type portable HC/O2 or CH4/O2 gas detector with an Infrared (NDIR) type sensor and galvanic cell type sensor. These sensors provide accurate detection of HC/O2(HC version) or CH4/O2(CH4 version) levels even in N2 and other inert environments. The measuring ranges are 0-100%LEL/0-100 vol% for HC or CH4 and 0-25 vol% for O2 respectively with automatic ranging. The RX-415 has explosion proof and Intrinsically Safe construction so that it can be used safely in any environment.

#### **SPECIFICATIONS**

Model	RX-415 (H	C version)	RX-415 (CH <sub>4</sub> version)		
Gas	НС	O <sub>2</sub>	CH4	O2	
Detection principle	NDIR (Non-Dispersive infrared)	Galvanic cell	NDIR (Non-Dispersive infrared)	Galvanic cell	
Range	0-100%LEL ( 0.5%LEL/digit) 0-100vol%( 0.5%vol/digit) (Auto range)	0-25vol%(0.1vol% / digit)	0-100%LEL ( 0.5%LEL/digit) 0-100vol%( 0.5%vol/digit) (Auto range)	0-25vol%(0.1vol% / digit)	
Response time	Within 30 seconds (T90)				
Sampling	Suction pump (built in)				
Ambient temp/humidity	-10°C∼+40°C / below 90%RH (Non-condensing)				
Power source	Alkaline batteries (Size C) 4pcs. (or Ni-Cd batteries (Size C) 4pcs.···Optional)				
Continuous operation time	Approx. 40 hours (no alarm or light, at 20°C)				
Explosion proof	Exiad Ⅱ BT3 (Alkaline batteries "Size C" only) (Pending)				
Dimension/weight	Approx. 200(W)×80(H)×142(D)mm/approx. 2 kg (including batteries)				
Alarm functions	Low battery voltage, Sensor connection failure, Sampling pump connection failure, System failure, Calibration failure (With failure message, alarm lamp and/or alarm buzzer)				
Feature	Peak hold, Self diagnosis				

<sup>·</sup> Specifications subject to change without notice.

#### STANDARD ACCESSORIES

Filter tube with flow monitor	ce
2 Connection tube (green) · · · · · · po	се
3 Spiral sampling tube ······1 po	ce
4 Gas sampling probe·····1 po	се
<b>⑤</b> Carrying case with shoulder strap ······1 po	ce
Alkaline battery (size C)4 po	cs
Operation manual ································ she	et

#### **OPTIONAL ACCESSORIES**

① Sampling tube (30m) ······1	рсе
② Gas sampling bag ······1	рсе
③ Ni-Cd battery charger ·····1	рсе

Notes: The calibration gas cylinder would be supplied from RKK local agent.





★Distributed by:

33248 Central Avenue Union City, CA 94587
Toll Free: (800) 754-5165 • Phone: (510) 441-5656 • Fax: (510) 441-5650 mail4rki@rkiinstruments.com • www.rkiinstruments.com